

TAB LETTER	USAF MISHAP REPORT CHECKLIST AND INDEX	NOT APPLICABLE	APPLICABLE NOT ATTACHED	ATTACHED
I. FACTS				
A	AF FORM 711			X
B	AF FORM 711A	X		
C	AF FORM 711B	X		
D	AF FORM 711C	X		
E	AF FORM 711D			X
F	AF FORM 711E	X		
G	FLIGHT AND PERSONNEL RECORDS	X		
H	AFTO FORM 781 SERIES	X		
I	MATERIEL DEFICIENCY REPORT	X		
J	TECHNICAL OR ENGINEERING EVALUATIONS OF MATERIEL (Department of Defense)	X		
K	DD FORM 175 OR AUTHORIZED SUBSTITUTE FLIGHT PLAN FORMS (See AFR 60-16)	X		
L	DD FORM 365F, WEIGHT AND BALANCE CLEARANCE FORM F	X		
M	CERTIFICATE OF DAMAGE (List of parts damaged) MANHOURS REQUIRED TO REPAIR, AND COST			X
N	TRANSCRIPTS OF RECORDED COMMUNICATIONS	X		
O	ANY ADDITIONAL SUBSTANTIATING DATA REPORTS			X
P	STATEMENT OF DAMAGE TO PRIVATE PROPERTY	X		
Q	ORDERS APPOINTING INVESTIGATING BOARD			X
R	DIAGRAMS (Fallout-impact area, etc.)	X		
S	PHOTOGRAPHS			X
II. BOARD OR INVESTIGATOR ANALYSIS				
T	INVESTIGATION, ANALYSIS, FINDINGS AND RECOMMENDATIONS 5 U.S.C. 552(b) (5) NOT RELEASABLE			X
U	STATEMENTS AND TESTIMONY OF WITNESSES AND PERSONS INVOLVED 5 U.S.C. 552(b) (4) & (5) NOT RELEASABLE			X
V	REBUTTALS			NOT RELEASABLE
W	TECHNICAL AND ENGINEERING EVALUATIONS OF MATERIEL (Contract) 5 U.S.C. 552(b) (4) & (5) NOT RELEASABLE			X
X	AF FORM 711F	X		NOT RELEASABLE
Y	AF FORM 711G 5 U.S.C. 552(b) (5) NOT RELEASABLE			X
Z	BOARD PROCEEDINGS 5 U.S.C. 552(b) (5) NOT RELEASABLE			X
WHENEVER "APPLICABLE BUT NOT ATTACHED" COLUMN IS MARKED FOR ANY OF THE ABOVE ITEMS, INFORMATION MUST BE ENTERED UNDER REMARKS TO INDICATE WHAT ACTION HAS BEEN TAKEN OR WILL BE TAKEN TO OBTAIN THE REQUIRED ATTACHMENT. LETTERED TABS SHOWN ABOVE WILL BE INSERTED FOR CORRESPONDING ATTACHED ITEMS, I.E., TAB G WILL ALWAYS BE USED FOR INDIVIDUAL FLIGHT RECORDS, TAB N FOR TRANSCRIPTS OF RECORDED COMMUNICATIONS. TABS WILL BE OMITTED ON THOSE ITEMS NOT APPLICABLE.				
REMARKS				

USAF MISHAP REPORT

(Fill in all spaces applicable. If additional space is needed, use additional sheet(s).)

1. DATE OF OCCURRENCE (Day, Month and Year) 18 April 1986		2. VEHICLE(S) OR MATERIEL INVOLVED (Model designation and serial no. if applicable) Titan 34D-9		3. FOR GROUND ACCIDENTS ONLY (Base Code and Report Serial No.) 86-4-18-701		
4. PLACE OF OCCURRENCE, STATE, COUNTY, DISTANCE AND DIRECTION FROM NEAREST TOWN, IF ON BASE, IDENTIFY, IF OFF BASE GIVE DISTANCE FROM NEAREST BASE. 800 Feet above Space Launch Complex 4, Vandenberg AFB CA			5. HOUR AND TIME ZONE LOCAL 1045 P.S.T.		6. <input checked="" type="checkbox"/> DAY <input type="checkbox"/> NIGHT <input type="checkbox"/> DAWN <input type="checkbox"/> DUSK	
7. ORGANIZATION POSSESSING OR OWNING VEHICLE OR MATERIEL AT TIME OF MISHAP						
MAJOR COMMAND AFSC	SUBCOMD OR AF SD	AIR DIVISION SAMTO	WING WSMC	GROUP 6595 ATG	SQ OR UNIT NAME & BASE CODE Vandenberg AFB CA (XUMV)	
8. (List organizations of second vehicle, if they differ from item 7 above)						
9. ORGANIZATION AND BASE SUBMITTING REPORT (Do not abbreviate) Titan 34D-9, Class A Space Mishap Investigation Board, HQ Air Force Systems Command, Andrews AFB, MD 20334						
10. LIST OF PERSONNEL DIRECTLY INVOLVED (See AFR 127-2 for specific instructions)						
LAST NAME, FIRST NAME, MIDDLE INITIAL	GRADE	SSAN	ASSIGNED DUTY	AERO RATING	DEGREE INJURY (Use Abbr)	DAYS LOST ON TT ONLY
None						
11. (Enter applicable letter(s) in DEGREE INJURY column. None-N; Temporary Total-TT; Permanent Partial-PP; Permanent Total-PT; Fatal-F; Missing-M)						
11. FACTUAL SUMMARY OF CIRCUMSTANCES. GIVE A DETAILED HISTORY OF FLIGHT OR CHRONOLOGICAL ORDER OF FACTS AND CIRCUMSTANCES LEADING TO THE MISHAP. THE RESULTS OF INVESTIGATION WILL BE CONTAINED IN THE "ANALYSIS PART" OF THE REPORT. ANALYSIS OF AND CONCLUSIONS DRAWN FROM ORAL OR WRITTEN STATEMENTS OBTAINED ONLY IN THE INTEREST OF MISHAP PREVENTION WILL NOT BE INCLUDED IN THIS SUMMARY. Launch of Titan 34D-9 from Vandenberg AFB, Space Launch Complex 4 East (SLC-4E) occurred at 1845:01.110 G.M.T., 18 Apr 86. During Stage 0 ascent, the vehicle was destroyed. The vehicle had just started its programmed roll maneuver to position itself to the correct flight azimuth for its flight profile at T+7.320 seconds. Review of telemetry data indicates anomolous conditions beginning at T+8.38 seconds. Shutdown was commanded at T+15.530 seconds with command destruct occurring at T+16.38 seconds. The vehicle impacted at T+28.44 seconds. The majority of the debris fell within the confines of SLC-4E damaging Ground Support Equipment. Burning debris created many small isolated fires within 1/2-mile of the complex.						
12. AUTHENTICATION						
CERTIFICATION BY (Title) Board President	TYPED NAME AND GRADE Nathan J. Lindsay Brigadier General	SIGNATURE <i>Nathan J. Lindsay</i>		DATE 8 June 86		

USAF MISHAP REPORT INDEX TAB

PART ONE - FACTS

- A** AF Form 711 - USAF Mishap Report
- B** AF Form 711a - Ground Mishap Report
- C** AF Form 711b - Aircraft Flight Mishap Report
- D** AF Form 711c - Aircraft Maintenance and Materiel Report
- E** AF Form 711d - Missile or Space Vehicle Mishap Report
- F** AF Form 711e - Explosives Mishap Report
- G** Flight and Personnel Records
- H** AFTO Form 781 Series
- I** Materiel Deficiency Report
- J** Technical and Engineering Evaluations of Materiel (DOD)
- K** DD Form 175 or Authorized Substitute Flight Plan Forms
- L** DD Form 365F, Weight and Balance Clearance Form F
- M** Certificate of Damage
- N** Transcripts of Recorded Communications
- O** Any Additional Substantiating Data Reports
- P** Statement of Damage to Private Property
- Q** Orders Appointing Investigating Board
- R** Diagrams (Fallout-Impact Area, etc.)
- S** Photographs

MISSILE OR SPACE VEHICLE MISHAP REPORT
(Fill in all spaces applicable. If additional space is needed, use additional sheet(s))

1. GENERAL INFORMATION

A. SERIAL NO. AND DESIGNATION OF AERO-SPACE VEHICLE(S) INVOLVED TITAN 34D-9	B. ASSIGNMENT OR STATUS CODE (AFR 65-110) 6595 ATG	C. HRS & TIME ZONE (Local) OF LAUNCH 1045 P.S.T.	D. DURATION OF FLIGHT HR. 0 MIN. 0 SEC. 8
E. ACTIVITY OR MANUEVER PRIOR TO ACCIDENT/INCIDENT INITIATED PROGRAMMED ROLL MANUEVER AT 7.32 SECONDS		F. ALT. OF ACFT IN RELATION TO TERRAIN (Actual or estimated) 800 FEET	G. VIOLATIONS <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

2. PHASE OF OPERATION (Check one)

TRANSPORTATION HANDLING COUNTDOWN INITIAL CLIMB RE-ENTRY RECOVERY OTHER (Specify)
 STORAGE PRECOUNTDOWN LAUNCH INFIGHT TERMINAL OR DUMP SERVICING OR MAINTENANCE

3. ACCIDENT TYPE

4. MISSION

(e.g. Fire or explosion on Launch or in air, intentional destruct or flight term., power failure in flight, loss of command guidance, flight control system, primary guidance system.) (e.g. Launch, training, maint. handling, operations alert, I&C Test)

EXPLOSION 8 SECONDS AFTER LAUNCH **CLASSIFIED**

5. WEATHER (At time and place of mishap)

SKY CONDITIONS 25,000 FEET SCATTERED	VISIBILITY 20 MILES	WIND DIRECTION AND VELOCITY-SURFACE AND ALTITUDES ON TRAJECTORY SURFACE - 6 KNOTS AT 350° 800 FEET - 18 KNOTS AT 320°
TEMPERATURE 58°F	HUMIDITY 60%	DEW POINT 44°F
OTHER WEATHER CONDITIONS (If weather was a factor in accident indicate and attach a statement of weather officer) WEATHER NOT A FACTOR		

6. MISSILE OR MSE DAMAGE INFORMATION

A. DAMAGE (Check one) <input checked="" type="checkbox"/> DESTROYED OR DAMAGED BEYOND ECONOMICAL REPAIR <input type="checkbox"/> REPAIRABLE <input type="checkbox"/> MISSING N/A		B. EST. NO. DIRECT MANHOURS FOR REPAIR, IF APPLICABLE (Including ALC hours)
COST OF DAMAGE	C. TO MISSILE (If destroyed, see T.O. 00-25-30) OVER \$29.8 MILLION	D. TO OPERATIONAL GROUND EQUIPMENT (Exclude normal residual damage) \$ 70 MILLION
E. FIRE OCCURRED <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, PRE-LAUNCH _____ LAUNCH _____ INFIGHT _____ ON IMPACT _____	F. EXPLOSION OCCURRED <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO IF YES, PRE-LAUNCH _____ LAUNCH _____ INFIGHT _____ ON IMPACT _____	G. T.O. IS NOT COMPLIED WITH AT TIME OF ACCIDENT TOTAL NUMBER N/A
H. MDR SUBMITTED <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO	I. PREVIOUS MDR'S SUBMITTED ON ANY FAC-TOR INVOLVED? IF YES, HOW MANY _____ <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO	J. FAILURE & CON-SUMPTION RE-PORT SUBMITTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO
K. TOR REQUESTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO		L. DULL SWORD SUB-MITTED <input type="checkbox"/> YES <input checked="" type="checkbox"/> NO

M. IDENTIFY REPORT NUMBERS A FACTORS ON ITEMS H, I, J, K, L, AS APPLICABLE AND ATTACH REPORTS (Include Work Unit and How Malfunction Codes)
N/A

7. LAUNCH FACILITIES

A. TYPE OF FACILITY TITAN 34D SPACE LAUNCH COMPLEX 4	B. IF FACILITY WAS A FACTOR IN THIS MISHAP, GIVE DETAILS FACILITY NOT A FACTOR
C. SUMMARIZE LAUNCH CLEARANCE WITH MILITARY OR CIVIL AGENCIES (If applicable) RANGE CONTROL OFFICER MISSILE FLIGHT CONTROL OFFICER LAUNCH DIRECTOR	D. TOXIC CHEMICALS INVOLVED <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO TYPE CHEMICALS N₂O₄ UDMI

8. AIRCRAFT INFORMATION

A. LAUNCH ACFT NDAS N/A	B. ACFT SERIAL NO. N/A	C. WAS AIRCRAFT DAMAGED? <input type="checkbox"/> YES <input type="checkbox"/> NO DEST. _____ SUB. _____ MINOR _____ MISSING _____	D. SPECIFY ACFT SYSTEM(S) CONTRIB. TO ACCT IF PERTINENT (Include Work Unit and How Malfunction Codes)
-----------------------------------	----------------------------------	---	---

9. OTHER USAF PROPERTY DAMAGE

A. TYPE OF PROPERTY DAMAGED (Fac. Bldg. Structures & other Government Equipment) N/A	B. REPAIR/REPLACEMENT COST \$ _____
--	--

10. NON- USAF PROPERTY DAMAGE

A. PROPERTY DAMAGE (Type and extent) N/A	B. COST OF DAMAGE \$ _____
--	-------------------------------

(When filled in)

EXPERIENCE OF KEY PERSONNEL							
A. LAUNCH EXPERIENCE		LAUNCHES SUPERVISED		LAUNCH EXPERIENCE		LAUNCHES SUPERVISED	
DUTY (As applicable)		TOTAL PREV	THIS MISSILE	DUTY (As applicable)		TOTAL PREV	THIS MISSILE
CONDOR OF UNIT POSSESSING MISSILE			31	RANGE SAFETY OFF (MSD)			8
FLIGHT/SITE COMMANDER			8	GROUND CONTROL OFFICER			
OPERATIONS OFFICER				GUIDANCE OFFICER			3
LAUNCH CONTROL OFFICER			10	OTHER GROUND PERS (Spec /yr)			
B. OTHER EXPERIENCE: IF MISHAP DID NOT OCCUR DURING LAUNCH, IDENTIFY PERSONNEL BY DUTY AND GIVE EXPERIENCE IN TYPE OF OPERATIONS IN PROGRESS; FOR EXAMPLE, PROPELLANT LOADING, PAD SETUP NO. OF WEAPONS LOADINGS, ETC.							
12. ENGINE(S)							
A. ENGINE INVOLVED <input checked="" type="checkbox"/> BOOSTER <input type="checkbox"/> TURBOJET <input type="checkbox"/> SUSTAINER <input type="checkbox"/> RAMJET <input type="checkbox"/> VERNIER <input type="checkbox"/> OTHER							
B. NAME, ENGINE MODEL, SERIAL NO. SOLID ROCKET MOTOR, MODEL 1206, SERIAL 122				C. MANUFACTURER AND DATE OF MANUFACTURE UNITED TECHNOLOGIES/CHEMICAL SYSTEMS DIV. 15 OCT 81 THRU 30 JAN 82			
D. ENGINE TIME (Hours, minutes) STATIC TEST, FLIGHT TEST, GROUND RUN UP N/A				E. POWERED FLIGHT TIME ON ACCIDENT INVOLVED ENGINE (Hr, min, sec) 8.766 SECONDS			
F. ENGINE TIME SINCE OVERHAUL (Hours, minutes) N/A				G. ENGINE OVERHAUL DEPOT OR FACILITY ACCOMPLISHING TDR N/A			
13. N/A GUIDANCE OR OTHER SYSTEM(S)							
A. NAME, MODEL, SERIAL NO.				B. MANUFACTURER, DATE OF MFR OF MALFUNCTIONING COMPONENT			
C. TIME IN SERVICE				D. OVERHAUL DEPOT OR FACILITY ACCOMPLISHING TDR (If applicable)			
A. NAME, MODEL, SERIAL NO.				B. MANUFACTURER, DATE OF MFR OF MALFUNCTIONING COMPONENT			
C. TIME IN SERVICE				D. OVERHAUL DEPOT OR FACILITY ACCOMPLISHING TDR (If applicable)			
14. N/A DESCRIPTION AND HISTORY OF MALFUNCTIONING COMPONENT(S)							
DESCRIBE PREVIOUS DISCREPANCIES OR DIFFICULTIES ENCOUNTERED INCLUDING SERVICES, MAINTENANCE AND OPERATIONAL DIFFICULTIES. SUMMARIZE INFORMATION THAT RELATES TO SPECIFIC FAILURE(S) OR MALFUNCTION(S)							

USAF MISHAP REPORT

INDEX TAB

PART ONE - FACTS

- A** AF Form 711 - USAF Mishap Report
- B** AF Form 711a - Ground Mishap Report
- C** AF Form 711b - Aircraft Flight Mishap Report
- D** AF Form 711c - Aircraft Maintenance and Materiel Report
- E** AF Form 711d - Missile or Space Vehicle Mishap Report
- F** AF Form 711e - Explosives Mishap Report
- G** Flight and Personnel Records
- H** AFTO Form 781 Series
- I** Materiel Deficiency Report
- J** Technical and Engineering Evaluations of Materiel (DOD)
- K** DD Form 175 or Authorized Substitute Flight Plan Forms
- L** DD Form 365F; Weight and Balance Clearance Form F
- M** Certificate of Damage
- N** Transcripts of Recorded Communications
- O** Any Additional Substantiating Data Reports
- P** Statement of Damage to Private Property
- Q** Orders Appointing Investigating Board
- R** Diagrams (Fallout Impact Area, etc.)
- S** Photographs


A
B
C
D
E
F
G
H
I
J
K
L
M

CERTIFICATE OF DAMAGE
TAB M

1. Launch vehicle acquisition cost: \$29.8 Million
2. Launch complex repair costs (material and labor estimates):

<u>Item</u>	<u>SLC-4E</u>	<u>SLC-4W</u>	<u>Total</u>
MST/UT Refurbishment	\$ 7.7M	\$ 4.6M	\$12.3M
AGE	9.3	0.7	10.0
Cabling/Air Conditioning	35.7	11.9	47.6
Roads and Grounds	0.1	0	0.1
			\$70.0 Million

I certify that the above information is accurate and current as of 28 May 1986. Launch complex repair costs are contractor estimates and constitute the best estimates available as of this date. Separate estimates for materials and labor are not available due to the methods used to make the estimates.



GEORGE A. STETZ, Colonel, USAF
Chief, Launch Operations and
Processing Team

USAF MISHAP REPORT

INDEX TAB

PART ONE - FACTS

- A** AF Form 711 - USAF Mishap Report
- B** AF Form 711a - Ground Mishap Report
- C** AF Form 711b - Aircraft Flight Mishap Report
- D** AF Form 711c - Aircraft Maintenance and Materiel Report
- E** AF Form 711d - Missile or Space Vehicle Mishap Report
- F** AF Form 711e - Explosives Mishap Report
- G** Flight and Personnel Records
- H** AFTO Form 781 Series
- I** Materiel Deficiency Report
- J** Technical and Engineering Evaluations of Materiel (DOD)
- K** DD Form 175 or Authorized Substitute Flight Plan Forms
- L** DD Form 365F, Weight and Balance Clearance Form F
- M** Certificate of Damage
- N** Transcripts of Recorded Communications
- O** Any Additional Substantiating Data Reports
- P** Statement of Damage to Private Property
- Q** Orders Appointing Investigating Board
- R** Diagrams (Fallout Impact Area, etc.)
- S** Photographs

- A**
- B**
- C**
- D**
- E**
- F**
- G**
- H**
- I**
- J**
- K**
- L**
- M**
- N**
- O**

I GENERAL BACKGROUND

1.0 INVESTIGATION BOARD STRUCTURE

1.1 ORGANIZATION

Colonel (Brigadier General selectee) Nathan J. Lindsay was named Board President and arrived at Vandenberg AFB, CA on 19 April 1986. The board convened at Vandenberg AFB on 21 April 1986 and was organized into panels to address specific investigation issues (Figure 1.1-1). The four major panels were Propulsion, Vehicle Systems, Launch Operations and Processing, and Range Systems. Two special panels were established: one to develop and analyze a mishap "fault tree", and a second to review and analyze all films and video coverage of the flight.

1.2 METHODOLOGY

The investigation was accomplished by interviewing witnesses, reviewing procedures and hardware designs/pedigrees; analyzing range systems, photographic information, booster and payload telemetry, and reconstructed debris; and developing failure scenarios. The Propulsion panel conducted its investigation at the United Technologies Corporation Chemical Systems Division (UTC/CSD), Aerojet TechSystems Company (ATC), Rohr Industries and Marshall Space Flight Center. The Vehicle Systems panel conducted its investigation at Vandenberg AFB and Martin Marietta Company (MMC), Denver CO. The Launch Operations and Processing panel and the Range Systems panel conducted their investigations at Vandenberg AFB.

2.0 TITAN 34-D FAMILIARIZATION

The Titan 34D (T34D) space launch vehicle is the latest configuration of the Titan III family, and evolved from the Titan IIIC development of 1961 (Figure 2.0-1). The T34D configuration has a different guidance system for each of the two launch sites. An inertial guidance system and upper stage for geosynchronous or low inclination trajectory is used when missions are launched from Cape Canaveral Air Force Station, FL. The T34D is used with a radio guidance system for polar or high inclination trajectory missions launched from Vandenberg Air Force Base, California.

To date, there have been 305 Titan launches. Of these, 145 have been various models of the Titan III series. Seventy-four vehicles were of the solid rocket motor assisted configurations--TIIIC, D, E, and 34D. This mishap occurred on the ninth launch in the 16 vehicle T34D series. Seven vehicles of this model remain to be launched. There has been one other failure of a T34D vehicle, number D-7, launched from Vandenberg AFB on 28 August 1985.

2.1 VEHICLE DESCRIPTION


The T34D configuration includes two large solid propellant rocket motors (Stage 0) and two liquid propellant central core stages, consisting of tankage and engines (Stage I and Stage II) (Figure 2.1-1).


2.1.1 Stage 0

Stage 0 consists of two identical, segmented solid propellant rocket motors (SRMs) (Figure 2.1.1-1) mounted 180° apart on the central core. Each 126-inch diameter SRM is 90.4 feet long; weighs 542,700 pounds and develops 1.4 million pounds of thrust. Each motor case (pressure vessel system)


Board Organization

0-2






Titan Family



NOTE: VEHICLE STATIONS AND UNLABELED DIMENSIONS ARE IN INCHES.

Titan 34D Configuration



SRM Configuration

consists of a forward closure, an aft closure, five interchangeable 126-inch long propellant segments, and a single 59-inch long propellant half-segment. Other components include the conical nozzle, forward and aft clusters of four solid propellant separation rockets, igniter, aft support skirt with heat shield, electrical/electronic distribution system for control and instrumentation, in-flight destruct system, and liquid injection thrust vector control system for steering.

2.1.1.1 The SRM segments are manufactured, without any seams, from a special tool steel (Figure 2.1.1.1-1). A single two-foot diameter steel billet is hot forged into a hollow cylinder. This cylinder is placed into a spinning drum, where the centrifugal forces press it along the drum's inner walls, increasing the length and diameter while thinning the segment walls. After cooling, the segment is placed on a steel drum on a large lathe and rolled into near final size. Final machining and heat treating produces a seamless cylinder with segment mating surfaces, without welded joints.






Figure 2.1.1.1-1 SRM Segment Manufacturing

2.1.1.2 The internal surface of each segment is insulated with a combination of silica-filled nitrile-butadiene rubber (NBR) and asbestos-filled NBR (Figure 2.1.1.2-1). The insulation components in each segment are the forward restrictor which prevents the forward surface of the propellant grain from igniting, the forward and aft relief boot which allows propellant shrinkage during cure to minimize stresses in the propellant and the sidewall insulation. To permit burning, the aft surface of the propellant is not insulated. The gap between the relief boot and sidewall insulation is filled with potting compound after propellant curing.

2.1.1.3 The propellant is a polybutadiene acrylic acid acrylonitrile (PBAN) composite which uses powdered aluminum fuel and ammonium perchlorate oxidizer. The plastic PBAN matrix also serves as fuel. The propellant in the six segments has a cylindrical center port which, together with the aft surface of each segment, forms the combustion surface. The forward closure, containing the gas generator type igniter, has an 8-point star internal burning grain configuration (Figure 2.1.1.3-1). The propellant is bonded to the insulation with an Al-123-26 liner which is sprayed onto the insulation before the propellant is cast.



SRM Forward Closure and Ignition System



SRM Segment-to-Segment Interface

2.1.1.4 The segments and closures are joined by a pin and clevis type joint (Figure 2.1.1.2-1), each held together by 240 cylindrical pins which are inserted by hand and held in place by a retaining strap. A gas pressure seal is provided by an insulator compression joint sealed with zinc chromate putty and a back-up O-ring in the segment joint.

2.1.1.5 The SRMs produce 1.4 million pounds of thrust when ignited and operate at an initial pressure of 810 PSIA after experiencing a peak ignition pressure pulse of 875 PSIA (Figure 2.1.1.7-1).

2.1.1.6 Steering during Stage 0 operation (Figure 2.1.1.6-1) is provided by the liquid injection thrust vector control (LITVC) system which is capable of producing a vector angle of $\pm 5^\circ$ and a maximum side force of 110,000 pounds per motor by injecting nitrogen tetroxide into the SRM nozzle through 24 electromechanical injection valves. The injection valves, operating in quadrant groups of six, are capable of being modulated from zero position to full open under guidance control from the core vehicle. Nitrogen tetroxide (N_2O_4) is provided to the valves from the TVC tank through a toroidal manifold that surrounds the nozzle. The cylindrical TVC tank, mounted externally on the SRM, is 320 inches long and 42 inches in diameter. The tank, which weighs 1113 pounds empty, carries 3424 pounds of N_2O_4 and 636 pounds of gaseous nitrogen. Initial pressure is 1350 PSIA and the system operates in a blowdown mode throughout the SRM mission.

2.1.1.7 Stage 0 operation is started with the receipt of the Fire Command, firing a pyrotechnic squib device and igniting the solid propellant igniter. The igniter burns for approximately one second, filling the main propellant grain bore with hot gas, igniting its propellant. The propellant burns along the entire central part of the SRM and on the aft end of each segment where a propellant burning surface is exposed (the forward facing surface is protected by a restrictor to prevent burning). The 8-point star grain in the forward closure ensures sufficient surface area for ignition. The SRM has a regressive thrust-time history (Figure 2.1.1.7-1), produced in part by the star configuration of the propellant grain in the forward closure. During the early phases of burning, this portion contributes much of the gas flow necessary to produce the high initial peak in the thrust-time curve. The design of the tapered bores and the forward restrictor in the individual segments provides a controlled burn of the propellant and ensures a predictable tail-off of thrust. The burn rate cannot be throttled and the engine burns until the propellant is depleted.

During the two minutes of SRM operation, the nominal sequence of events is as follows:

T-0:	SRM ignition.
T+400 ms:	Lift-off.
T+500 ms:	SRM chamber pressure peak at 880 PSIA. Maximum thrust is achieved.
T+6 sec:	Vehicle begins a roll maneuver to the flight azimuth.
T+10 sec:	Vehicle begins a pitch maneuver aiming itself down range.
T+55 sec:	Maximum aerodynamic pressure occurs.
T+63 sec:	Forward closure propellant is consumed, leaving propellant burning in the segments and aft closures of both boosters.
T+82 sec:	Aft closure propellant is consumed.





Figure 2.1.1.6-1 Thrust Vector Control System



SRM Thrust/Pressure Profile

- T+102 sec: End of web action time is reached, and the motors are tailing off. Approximately 17,000 lbs of solid propellant remains in each motor.
- T+110 sec: The Titan core vehicle senses decrease in vehicle acceleration initiating the ignition of the Stage 1 engines and a ten second countdown for solid motor separation.
- T+120 sec: Explosive bolts release the forward outriggers and the aft attachment fittings which connect the solid rocket motors to the core vehicle. Staging rockets, four forward and four aft on each booster, fire and push the spent solid rocket motor away from the core.

2.1.2 Stage I

Stage I consists of a liquid propellant rocket engine attached to an airframe which includes the fuel and oxidizer tanks, between tank structure, forward skirt and aft skirt (Figure 2.1.2-1). The Stage I engine is mounted on a single frame and configured as a single propulsion unit consisting of two independently operating thrust chambers and their respective turbine-driven pump assemblies. The Stage I engine develops a total of 529,000 pounds (vacuum) thrust. The fuel and oxidizer tanks are welded structures consisting of a forward dome, barrel section and aft dome. They are mounted in tandem with the oxidizer tank located above the fuel tank. The fuel tank has an internal conduit to duct the oxidizer to the rocket engine. The between-tank structure and the skirts have welded frames to which the aerodynamic surface is riveted. A "boattail" heat shield of aluminum encloses the Stage I engine components to protect them from the radiant heat produced by the exhaust plume of the Stage 0 rocket motor. Thrust vector control is accomplished by gimbaling the engine thrust chamber to provide pitch, yaw, and roll corrections. Hydraulic actuators, driven from the engine turbopump and controlled by electrical signals from the guidance and flight control system, provide the gimbal force.

2.1.3 Stage II


Stage II uses a single liquid propellant rocket engine attached to an airframe and is similar in construction to Stage I. The rocket engine delivers 100,000 pounds of thrust (vacuum) using one thrust chamber and nozzle and is smaller than a single Stage I thrust chamber. Thrust vector control is accomplished by gimbaling the chamber, but roll control, which is impossible using only one nozzle, is provided by ducting pump turbine exhaust through a swiveled nozzle.

The Stage II airframe consists of a transition assembly for attachment of an upper stage or payload, oxidizer tank, between-tank structure, fuel tank, and aft skirt. An interstage structure connects Stages I and II. Since Stage I shutdown and Stage II ignition are simultaneous, blast ports are provided in the interstage structure to relieve gas pressure in the Stage II engine compartment during the period between Stage II ignition and physical stage separation. The interstage structure is made from aluminum skin riveted to a welded frame. The Stage II propellant tanks are similar in structure to those of Stage I.

2.1.4 Destruct System

The T34D destruct system (Figure 2.1.4-1) causes flight termination through destruction of the vehicle when directed by the Range Safety Officer (RSO) or by the on-board Inadvertent Separation Destruct System (ISDS). High explosive destruct wafers are located between the Stage I and Stage II fuel and oxidizer tanks and linear shape charge on the SRMs.



The ISDS is a safety feature intended to destroy Stage I or the SRMs in case of premature separation. It is located on both Stage I and the SRMs and ties directly into the destruct package. An ISDS is not needed on Stage II since the command destruct receivers, which are on Stage II, may be utilized to destroy this stage after an inadvertent separation.



Core Vehicle Configuration

2.1.4.1 Each core destruct package consists of an initiator, three legs of ordnance primacord circuitry with boosters, and two bidirectional destruct charges. (Figure 2.1.4-1)


2.1.4.2 The SRM ISDS is a "hot-wire" activated, electronic system that requires the loss (breaking) of redundant hot wires and safety ground wires between the SRM and the core vehicle prior to activation. The destruct system consists of a linear shaped charge that splits each metal case segment down its length, jumpers to conduct the shock wave across segment interfaces, a linear shaped charge to split the thrust vector control (TVC) tanks, and a jumper to connect the main SRM charge to the TVC tank (Figure 2.1.4-1). The primary function of the SRM ISDS is to activate destruct in the event that the command link is lost due to premature separation of the SRM from the core vehicle. The ISDS is disabled prior to normal separation of the SRMs on command from the core vehicle.



T34D Destruct System

2.1.5 Flight Profile


The flight profile, typical of the T34D launches from Vandenberg AFB, is depicted in (Figure 2.1.5-1). The profile shows the normal events from lift-off to payload separation.



T34D Flight Profile

2.1.6 Vehicle Guidance

For launches from Vandenberg AFB, the T34D uses a combination of an on-board, preprogrammed, open-loop guidance system and ground-based radio guidance. The on-board computer's preprogrammed "path" contains a nominal flight profile, while the ground guidance corrects for vehicle performance dispersions. Stage II contains the Titan's flight computer, three axis attitude reference (TARS) package and airborne radio guidance system receiver and beacon.



Vehicle Accelerometer Data







Figure 2.3-3 SRM-2 Manifold Pressure



Payload Roll Rate Data



STAGE I FUEL SUCTION PRESSURE




STAGE I OXIDIZER SUCTION PRESSURE


Fuel/Oxidizer Pressure

UT	TIME			EVENT	SOURCE	COMMENT
	P/L	Y+	Uncert(msec)			
12:43:00.650	67.0	0.0	-1/+0 ±2.5	SEM Ignition	TM / Photos	Nominal
101.110	67.460	0.440	"	Liftoff	TM (IC18) / Photos	Nominal
101.243	67.593	0.593	"	Electrical Disconnect	TM (IC18) / Photos	Nominal
104.53- 108.25	71.20- 74.60	4.20- 7.60	-40/+0	Roll Signature Differs from E-4	P/L Roll Gyro TM	Unanticipated Roll (1)
107.49- 107.78	73.84- 74.14	4.84 7.14	+20	Change to Automatic Frequency Control (APC)	AT&T Ground Guidance Data	Unanticipated Change in APC
107.97	74.32	7.32	-10/+0	Programmed Roll Cmd	TM	Nominal
108.42	74.77	7.77	-5/+0 -1/+0	Vehicle Programmed Roll Begins (1412)	P/L Roll Gyro TM Booster TM	Expected Change in Roll Rate
109.410- 109.417	75.760- 75.747	8.760- 8.747	-15.8	Flare Flash Observed	Flare	First Visible Evidence of Explosion (412.90/412.91)
109.4141- 109.4164		8.7641 -2.5/+0 8.7646 -1/+0		STG 1 Vert Accel (2305) Disturbance	TM	-0.30 pitch
109.4129- 109.4179		8.7629 -5/+0 8.7629 -1/+0		SEM2 Injectant Manifold Press #2 (5232) Decreases	TM	Pressure drops from 1050 to 918 PSIA
109.4160- 109.4210		8.7600 -5/+0 8.7711 -1/+0		Large change in Roll Rate (1212)	TM	TARS senses large change in roll rate (sign probably OK, magnitude questionable)
109.4160- 109.4185		8.7660 -2.5/+0 8.7683 -1/+0		Fuel Suction Pressure (775-2) Drops (1570)	TM	Fuel Pressure drops from 10.1 to 8.8 PSIA
109.4140- 109.4185		8.7660 -2.5/+0 8.7683 -1/+0		STG 1 Lateral Accel (2304) Saturates	TM	+2.50 yaw
109.4166- 109.4191		8.7666 -2.5/+0 8.7691 -1/+0		STG 1 Long Accel (2308) Saturates	TM	-2.50
109.4166- 109.4191		8.7666 8.7691		STG 1 Vert Accel (2305) TH Change (0.80/2.3 ms)	TM	+0.50
109.4148- 109.4198		8.7648 -5/+0 8.7798 -1/+0		SEM2 Injectant Manifold Press #1 (5231) Decreases	TM	Pressure drops from 1032 to 818 PSIA
109.4178- 109.4203		8.7678 -2.5/+0 8.7703 -1/+0		Fuel Suction Pressure (775-1) Drops (1515)	TM	Fuel Pressure drops from 49.8 to 31.8 PSIA
109.4199- 109.4209		8.7699 -1/+0 8.7709		1st indication of shorted data lines (1341)	TM	Drop outs in data imply shorts in TM harness
109.4213		8.7713 -1/+0		Short Cleared (2909)	TM	TM returns to normal
109.4219		8.7719 -1/+0		SEM2 TM lines open (3209)	TM	Data starts tracking previous sample (due to line capacitance)
109.4244- 109.4248		8.7744 -1/+0 8.7748		39.3 as expected - all data appears bad	TM	Apparent line shorts in TM data
109.4248- 109.4254		8.7748 -0.6/+0 8.7754 -1/+0		Oxidizer Suction Press (775-2) (1518) Drops	TM	Ox Pressure drops from
109.4308		8.7808 -1.25/+0 -1/+0		Perturbations on SEM2 Destruct Amplifiers (5207/5208)	TM	
109.4378 109.4804		8.8298 -1.25/+0 8.8308		Stage 1 Electrical Disconnect	TM	Loss of Stage 1 TM
109.447- 109.500		8.827- 8.830		1st ox espous appear	File	TM tank ruptured (2)
109.498		8.848		SEM2 approx. early move	File	Physical breakup begins (3)
109.644- 109.708		8.984- 9.058		SEM1 movement	File	
109.477- 109.787		9.027- 9.137		STG1 Ox Cloud appears	File	STG1 Ox tank ruptured
109.754- 109.787		9.114- 9.137		SEM1 ISDS	File	SEM1 Inadvertent Separation Destruct. Svc operation
110.193- 110.268		9.453 9.618		STG2 Ox Cloud appears	File	STG2 Ox tank ruptured
116.18		15.53		Commanded Shutdown	Range	
117.03		16.38		Command Destruct	Range	
119.09		20.44		Loss of Signal (Total Breakup, nice ground)	Range, AT&T	Total loss of guidance signal, TM from Booster & P/L

Flight Timeline



SRM-2 Nose Motion History






Figure 1.2.2.1-1 Sensor Locations (Boattail)

	I340-9	EIR	DESIGN
PRESSURE BAFFLE BASE (MEAS. P17A)	+3.5, -2.0*	+8.2, -3.1 (TIIE-05)	+11.75, -4.36
PRESSURE BAFFLE SIDE SENSING PORT TOWARD SRM (MEAS. P19)	MEASUREMENT* DRIFTED	+3.7, -2.0 (TIIE-05)	
INSIDE BAFFLE SENSING (MEAS. P23, P25)	+1.35, -0.6	NO COMPARABLE DATA	BASE +3.22, -1.61 TOP +2.35, -1.18
INSIDE BOATTAIL (AIRBORNE MEAS. 2300)	+0.73, -0.56	NO COMPARABLE DATA	-1.66 ESTIMATED FROM VENTING ANALYSIS

* POST TEST CALIBRATION OF SENSORS IN PROCESS

NOTE: ALL DATA ARE IN ΔP -PSI

Overpressure Data

Sample Debris Log


61-0

TAG	SUF#	BS/D	BS/H	R/P	REF D1ST	AC/D	ACTUAL D1ST	CONTRACTOR	DESCRIPTION
00040			204	12	A	1092.88	290	MHC	OUTRIGGER THURSTERS
00130								MHC	AFT FUEL SKIRT 10
00143			67	40	U	404.26	58	MHC	CORE SKIN 32" X 20"
00149			30	35	E	401.55	39	MHC	CORE TANK SKIN 36" X 20"
00153			37	4	E	259.32	29	MHC	CORE SKIN 28" X 14"
00160			184	43	E	205.83	321	MHC	INTER STAGE SECTION 5--LONG 2.5" WIDE
00162			154	43	E	205.83	321	MHC	RING P/N B0801226021-009
00163			760	28	E	108.53	320	MHC	SKIN
00164			160	28	E	108.53	320	MHC	STRINGER
00164			136	5	E	225.98	335	MHC	FWD END FUEL TANK BARREL STAGE 1
00178			250	27	I	50.21	317	MHC	CORE WIRING & BRACKETS (2 PCS) R1600044231-210 1.7X 3"
00181			12	4	E	50.21	317	MHC	CORE TANK STRINGER 7" X 1 1/2"
00182			12	4	E	100.46	306	MHC	CORE RELAY 37 X 4"
00183			348	15	E	100.46	306	MHC	CORE RELAY 37 X 4"
00184			348	15	E	100.46	306	MHC	CORE STRINGER 40" X 3"
00187			99	7	I	655.14	250	MHC	HOSE ASSY
00188			48	28	I	680.80	214	MHC	ALUM PANEL 10"X14"
00196			176	0	U	630.41	273	MHC	ALUM PANEL 10" X 18"
00255			170	0	U	507.04	270	MHC	ALUM TANK PART
00268			267	16	B	81.42	287	MHC	SOLE CONTROL ACT ARM
00321			109	15	A	271.57	249	MHC	AFT SKIRT CORE VEHICLE
00354			109	15	A	307.08	244	MHC	STG 1 AFT FUEL SKIRT AFT FRAME & FLOOR TRUS/10816000020
00359			115	54	A	337.08	244	MHC	ELECTRICAL BOXES
00360			115	54	A	337.08	244	MHC	ELECTRICAL POWER SUPPLY WITH MOUNT BK1 (FLOW LVL SENSOR)
00361			115	54	A	348.90	241	MHC	ELECT CONNECTORS/LEADS
00362			109	26	A	348.90	241	MHC	TINER 510 SKIRT
00367			98	14	A	257.80	241	MHC	STG 1 FUEL TANK SKIRT
00369			92	4	A	257.80	241	MHC	BOAT TAIL FLOOR
00396			70	12	I	302.98	230	MHC	FLANGED WITH ELECT CONDUIT ALUM CAST 3" WIDE X 2' LONG
00398			79	14	A	306.99	232	MHC	ACTUATOR PUSHING MOUNTING BRACKET
00399			49	14	A	362.95	233	MHC	ACTUATOR PUSHING MOUNTING BRACKET
00405			959	55				MHC	SOULTE I BEAM CONNECTION (S41455-010 MALCO)
00406			959	55				MHC	AFT SKIRT STG 1 ACCOMMODATED BY OTHER SMALL PIECES
00407			959	55				MHC	STG 1 AFT SKIRT
00408			930	99				MHC	STG 2 FUEL AFT DOME REF ITEM 433
00437			0	0				MHC	STAGE 2 FUEL AFT DOME REF ITEM 433
00440			0	0				MHC	STRIBRIGER FROM INTERSTAGE REF ITEM 433
00447			0	0				MHC	RESISTOR BOX REF ITEM 433
00448			0	0				MHC	STAGE 2 TANK BOTTOM DEFUSER REF ITEM 433
00449			0	0				MHC	STG 2 MAINMAN CLAMP COOLER/NSVR LOC NE OF RET BASIN
00450			0	0				MHC	FUEL TANK BURNST DISK (STAGE 2) LOC MIDDLE OF RET BASIN
00457			0	0				MHC	BOAT TAIL FRAME LOC NE OF RET BASIN
00458			0	0				MHC	STAGE 1 AFT KING FRAME LOC 15 S RET BASIN DECK
00462			0	0				MHC	BOAT TAIL FRAME LOC 13 S RET BASIN DECK
00463			0	0				MHC	HYDRAULIC PUMP SPRING AND CAP PART OF 462
00464			0	0				MHC	BOAT TAIL FRAME MEMBER LOC 9" N RET BASIN DRAIN


05/13/96

J499 DEBRIS IDENTIFICATION-INCLUDES CALCULATED VALUES

PAGE 1



TYPICAL
71° THRU 198°






DEPARTMENT OF THE AIR FORCE
USAF HOSPITAL, VANDENBERG (SAC)
VANDENBERG AIR FORCE BASE, CALIFORNIA 93437

19 May 1986

Memo for Colonel Knoll

Subject: Visit to Hollister Ranch

1. On 4 May 1986, we accompanied Colonel R. Knoll to Hollister Ranch. We met with some 15 to 20 residents of the area concerning the Titan accident on 13 April 1986. This visit was in response to Mrs. Boise's letter of 21 April 1986 (see attached).
2. Residents commented that a white cloud came rapidly down the coast after the explosion. Some noted skin and eye irritation immediately after being caught up in the cloud. A few complained of sore throats and a cough for several days thereafter.
3. Residents also expressed their concern about radiation exposure. We explained that there were no licensed sources on board but that there was a small quantity of magnesium-thorium structural material on board. We assured them that this was not a significant hazard and that the material was all recovered.
4. The results of our meeting left us with the impression that the residents were exposed to some agents evolved from the accident. Our opinion is that they were probably exposed to low levels of Al_2O_3 and HCl with a resulting mild irritation of skin and mucous membranes. No significant sequelae from the exposure should be anticipated.
5. Future launches, particularly those involving SLC-6, should consider the unusual dispersal patterns of toxic gases and aerosols formed during nominal and worst-case scenarios. The effects that were reported at Hollister as well as other reports from Jalama Beach and the Channel Islands imply that under certain conditions, toxic exposures could be experienced at extraordinary distances from Vandenberg.


JERRY M. MORFORD, Major, USAF, BSC
Chief, Bioenvironmental Engineering Services

ALLEN J. PARMET, Major, USAF, MC
Chief, Aerospace Medicine

2 Atchs

1. Ltr, 21 Apr 86 - Mrs. Boise
2. Ltr, 9 May 86 - Mrs. Boise

Monday, April 21, 1986

Dear Commander,

your rocket explosion last Friday, April 18th has infected my children. They were all exposed to the toxic cloud. They were not given the advantage of any warning or any information on the toxic material in the air surrounding them.

The location of this exposure is near Point Conception - on the west end of the Hollister Ranch. Two calls (that I know of) were made to Vandenberg Air Force Base with the questions "what is in the air? Is it dangerous to humans or animals?" The reply from VAFB was "we are not allowed to give any information."

our first knowledge of the explosion was when a neighbor (also a resident on the Hollister Ranch) came by and told us he had seen the explosion and the huge orange cloud and was evacuating and urged us to do the same. our children hurried to where other family members

were and warned them of the disaster.

That is when they called - VAFB and were given the no comment answer.

I understand the sheriff came to the front gate at the Hollister Ranch and declared the air safe at that location. That is 10-15 miles east of Pt. Conception and the air quality was entirely different where our children were exposed.

What I want to know is this:

Why - consent we have had the privilege of a warning - or some helpful information on the phone?

What - are the toxic effects of this chemical on human beings? Was the rocket solar powered or atomic powered?

Who - do we deal with on this matter?

Who - do we call when another disaster of this nature affects us?

Who - is going to warn us next time?

I hope you will reply with answers to my questions.

Sincerely,
Martha T. Boie
Parcel # 41
Hollister Ranch
Gardner CA 951

a few give you names of men
proper that I am aware of who were
and supposed if you request that information

- Benny Boy count
- Ernest Boy count (6 months)
- Kit Boy count
- Brenda Boy
- Sam Pitt (boyfriend of Brenda)
- Eileen M. Boy
- Philip T. Boy

our former members who were
supposed to the list should be:

May 9, 1986

Dear General Walbins,

Thank you for your prompt response


to my letter after the rocket explosion.

We are very grateful to Col. Kneel, Dr. Parmet
and Lt. Col. Meyford for coming to see us at
the Hollister Ranch on Sunday afternoon, May 4th

My conclusion is that we now have
a line of communication going between us.
We will work out a system where the
residents of the Hollister Ranch will have
prompt, correct information in the event of
another mishap.

Thank you again for your part
in helping us work together to solve
this matter.

Sincerely,
Martha T. Boise
Parcel # 41
Hollister Ranch
Gaviota, CA. 93117



STAGE 1 VERTICAL ACCELERATION

STAGE 1 LATERAL ACCELERATION

STAGE 1 LONGITUDINAL ACCELERATION

SRM 2 TVC MANIFOLD RUPTURED

SRM 2 MANIFOLD PRESSURE # 2


SRM 2 MANIFOLD PRESSURE # 1


STAGE 1 FUEL TANK RUPTURED


FUEL SUCTION PRESSURE (PFS-# 2)


FUEL SUCTION PRESSURE (PFS-# 1)

One Frame Prior to Event
T+8.729 Seconds
(Film 622.50, Frame -1).











First Frame Showing Event
T+8.771 Seconds
(Film 622.50, Frame 0)




SRM-1, ISDS Destruct (612.10 Fm +13)



SRM-1, ISDS Destruct (612.10 Fm +14)

Fireball Expanding
1+8.812 Seconds
(Film 622.50, Frame +1)






SRM-1, ISDS Destruct (612.10 Fm +15)


Fireball Expanding
1+8.854 Seconds
(Film 622.50, Frame +2)








SRM-2 Motion (622.50, Fm +2)
















S-17

S-18





USAF MISHAP REPORT INDEX TAB PART ONE - FACTS

- A** AF Form 711 - USAF Mishap Report
- B** AF Form 711a - Ground Mishap Report
- C** AF Form 711b - Aircraft Flight Mishap Report
- D** AF Form 711c - Aircraft Maintenance and Materiel Report
- E** AF Form 711d - Missile or Space Vehicle Mishap Report
- F** AF Form 711e - Explosives Mishap Report
- G** Flight and Personnel Records
- H** AFTO Form 781 Series
- I** Materiel Deficiency Report
- J** Technical and Engineering Evaluations of Materiel (DOD)
- K** DD Form 175 or Authorized Substitute Flight Plan Forms
- L** DD Form 365F, Weight and Balance Clearance Form F
- M** Certificate of Damage
- N** Transcripts of Recorded Communications
- O** Any Additional Substantiating Data Reports
- P** Statement of Damage to Private Property
- Q** Orders Appointing Investigating Board
- R** Diagrams (Fallout-Impact Area, etc.)
- S** Photographs



DEPARTMENT OF THE AIR FORCE
HEADQUARTERS AIR FORCE SYSTEMS COMMAND
ANDREWS AIR FORCE BASE DC 20334-5000

SPECIAL ORDER

12 May 1986

M-23

The Commander AFSC has appointed the following personnel to serve as members of the Safety Investigation Board for the purpose of investigating the Class A space mishap which occurred 18 April 1986 involving Titan 34D-9 at Vandenberg AFB CA. This duty will take precedence over all other duties. Authority: AFR 127-4, para 3-4.

<u>Grade</u>	<u>Name</u>	<u>SSAN</u>	<u>Organization</u>	<u>Clearance</u>
<u>PRESIDENT</u>				
COL	NATHAN F. LINDSAY		ESMC/CC	Top Secret
<u>VICE PRESIDENT</u>				
COL	AUBREY MCALPINE		SAF/SS	Top Secret
<u>PROPULSION GROUP</u>				
COL	LARRY JACKSON		SD/YA	Top Secret
LT COL	AL BLAHO		AFCMO	Top Secret
	ROBERT GEISLER		AFRPL/DY	Top Secret
	WILBUR W. WELLS		AFRPL/MKB	Top Secret
<u>VEHICLE SYSTEMS GROUP</u>				
COL	JAMES MANNEN		SD/DAAX	Top Secret
LT COL	ERIC E. SUNDBERG		HQ SPACECMD/DOT	Top Secret
MAJ	EDWIN A. BLANKINSHIP		SD/YG	Top Secret
MAJ	JOHN CUNNINGHAM		SD/YD	Top Secret
<u>LAUNCH OPERATIONS AND PROCESSING GROUP</u>				
COL	GEORGE STETZ		6595 STG	Top Secret
LT COL	JERRY M. JOHNSON		6555 ASTG	Top Secret
CAPT	MIKE G. WOOLLEY		6555 ASTG	Top Secret

M-23

<u>Grade</u>	<u>Name</u>	<u>SSAN</u>	<u>Organization</u>	<u>Clearance</u>
--------------	-------------	-------------	---------------------	------------------

RANGE SYSTEMS REVIEW TEAM

LT COL	WILLIE W. GRAY		ESMC/RO	Top Secret
LT COL	WILLIAM CHRISTENSEN		USAFSAM/EVK	Top Secret
MAJ	GERALD F. BIERINGER		ESMC/SE	Top Secret
MAJ	E. GEORGE WOLF, JR.		USAFSAM/EVH	Top Secret
	KENNETH L. KAISLER		ESMC/SEM	Top Secret
	LOUIS T. ULLIAN		ESMC/SEM	Top Secret

SUPPORT TEAM

COL	FREDERICK W. WEIL	1	WSMC	Top Secret
1LT	RICHARD F. MAFFEI (Recorder)	1	SD/YXD	Secret

ADVISORS

MAJ	BARRY L. RICHARD		SD/SE	Top Secret
	ALEX MCCOOL		Marshall Space Flight Center	Top Secret
	ROBIN STEVENSON		Aerospace Corp	Top Secret
	WILLIAM DRAKE		Aerospace Corp	Secret
	JOHN WILLACHER		Aerospace Corp	Secret
	OTTO BENDER		Aerospace Corp	Secret
	MERRITT BIRKY		NTSB	None
	ROBERT MCGUIRE		NTSB	None

This special order revokes M-21, 28 April 1986.

FOR THE COMMANDER



DENIS SABBELIN, Colonel, USAF
Director of Administration

DISTRIBUTION:

2 - IGF
1 - Each Individual
1 - DA
1 - File

USAF MISHAP REPORT INDEX TAB

PART ONE - FACTS

- A** AF Form 711 - USAF Mishap Report
- B** AF Form 711a - Ground Mishap Report
- C** AF Form 711b - Aircraft Flight Mishap Report
- D** AF Form 711c - Aircraft Maintenance and Materiel Report
- E** AF Form 711d - Missile or Space Vehicle Mishap Report
- F** AF Form 711e - Explosives Mishap Report
- G** Flight and Personnel Records
- H** AFTO Form 781 Series
- I** Materiel Deficiency Report
- J** Technical and Engineering Evaluations of Materiel (DOD)
- K** DD Form 175 or Authorized Substitute Flight Plan Forms
- L** DD Form 365F, Weight and Balance Clearance Form F
- M** Certificate of Damage
- N** Transcripts of Recorded Communications
- O** Any Additional Substantiating Data Reports
- P** Statement of Damage to Private Property
- Q** Orders Appointing Investigating Board
- R** Diagrams (Fallout-Impact Area, etc.)
- S** Photographs

- A**
- B**
- C**
- D**
- E**
- F**
- G**
- H**
- I**
- J**
- K**
- L**
- M**
- N**
- O**
- P**
- Q**
- R**